Main PCBA service

1

Unplug throttle, brake and clutch RJ12 cables from main PCBA

2

Place the Hex key 4 on the screw and kick it a bit with a hammer so it fits better


3

Unscrew the screw with Hex key 4

Repeat steps 2 and 3 with remaining two screws

4

Remove the footrest plate and place it safely


5

Unplug both vibration motor cables from main PCBA

6

With Socket wrench insert 5.5 remove 4 nuts which hold main PCBA

7

Remove main PCBA


8

Put new PCBA on its place

9

Turn back 4 nuts with Socket wrench insert 5.5

10

Plug in vibration motor cables in ports on main PCBA

11

Turn back the footrest plate on its place

12

With Hex key 4 turn back 3 screws which hold footrest plate

13

Plug in throttle, brake and clutch RJ12
cables in main PCBA

TEST THE PEDALS!